

Conversion

Conversion Chart

INCHES			INCHES			INCHES		
FRCTN.	DEC.	MM	FRCTN.	DEC.	MM	FRCTN.	DEC.	MM
-	.0004	.0100	-	.5118	13.0000	-	1.2205	31.0000
-	.0040	1.0000	33/64	.5156	13.0970	1-1/4	1.2500	31.7500
-	.0100	2.5000	17/32	.5310	13.4940	-	1.2598	32.0000
1/64	.0156	3.9700	35/64	.5470	13.8910	1-9/32	1.2810	32.5440
-	.0197	5.0000	-	.5512	14.0000	-	1.2992	33.0000
-	.0295	7.5000	9/16	.5630	14.2880	1-5/16	1.3120	33.3380
1/32	.0313	7.9400	-	.5710	14.5000	-	1.3386	34.0000
-	.0394	1.0000	37/64	.5790	14.6840	1-11/32	1.3440	34.1310
3/64	.0469	1.1910	-	.5906	15.0000	1-3/8	1.3750	34.9250
-	.0590	1.5000	19/32	.5940	15.0810	-	1.3779	35.0000
1/16	.0620	1.5880	39/64	.6090	15.4780	1-13/32	1.4060	35.7190
5/64	.0781	1.9840	5/8	.6250	15.8750	-	1.4173	36.0000
-	.0787	2.0000	-	.6299	16.0000	1-7/16	1.4380	36.5130
3/32	.0940	2.3810	41/64	.6406	16.2720	-	1.4567	37.0000
-	.0984	2.5000	-	.6496	16.5000	1-15/32	1.4690	37.3060
7/64	.1090	2.7780	21/32	.6560	16.6690	-	1.4961	38.0000
-	.1181	3.0000	-	.6693	17.0000	1-1/2	1.5000	38.1000
1/8	.1250	3.1750	43/64	.6720	17.0660	1-17/32	1.5310	38.8940
-	.1378	3.5000	11/16	.6875	17.4630	-	1.5354	39.0000
9/64	.1410	3.5720	45/64	.7030	17.8590	1-9/16	1.5620	39.6880
5/32	.1560	3.9690	-	.7087	18.0000	-	1.5748	40.0000
-	.1575	4.0000	23/32	.7190	18.2560	1-19/32	1.5940	40.4810
11/64	.1720	4.3660	-	.7283	18.5000	-	1.6142	41.0000
-	.1770	4.5000	47/64	.7340	18.6530	1-5/8	1.6250	41.2750
3/16	.1875	4.7630	-	.7480	19.0000	-	1.6535	42.0000
-	.1969	5.0000	3/4	.7500	19.0500	1-31/32	1.6562	42.0690
13/64	.2030	5.1590	49/64	.7656	19.4470	1-11/16	1.6875	42.8630
-	.2165	5.5000	25/32	.7810	19.8440	-	1.6929	43.0000
7/32	.2190	5.5560	-	.7874	20.0000	1-23/32	1.7190	43.6560
15/64	.2340	5.9530	51/64	.7970	20.2410	-	1.7323	44.0000
-	.2362	6.0000	13/16	.8125	20.6380	1-3/4	1.7500	4.4500
1/4	.2500	6.3500	-	.8268	21.0000	-	1.7717	45.0000
-	.2559	6.5000	53/64	.8280	21.0340	1-25/32	1.7810	45.2440
17/64	.2656	6.7470	27/32	.8440	21.4310	-	1.8110	46.0000
-	.2756	7.0000	55/64	.8590	21.8280	1-13/16	1.8125	46.0380
9/32	.2810	7.1440	-	.8662	22.0000	1-27/32	1.8440	46.8310
-	.2953	7.5000	7/8	.8750	22.2250	-	1.8504	47.0000
19/64	.2970	7.5410	57/64	.8906	22.6220	1-7/8	1.8750	47.6250
5/16	.3120	7.9380	-	.9055	23.0000	-	1.8898	48.0000
-	.3150	8.0000	29/32	.9062	23.0190	1-29/32	1.9062	48.4190
21/64	.3280	8.3340	59/64	.9220	23.4160	-	1.9291	49.0000
-	.3350	8.5000	15/16	.9375	23.8130	1-15/16	1.9375	49.2130
11/32	.3440	8.7310	-	.9449	24.0000	-	1.9685	50.0000
-	.3543	9.0000	61/64	.9530	24.2090	1-31/32	1.9690	50.0060
23/64	.3590	9.1280	31/32	.9690	24.6060	2	2.0000	50.8000
-	.3740	9.5000	-	.9843	25.0000	-	2.0079	51.0000
3/8	.3750	9.5250	63/64	.9844	25.0030	2-1/32	2.0313	51.5940
25/64	.3910	9.9220	1	1.0000	25.4000	-	2.0472	52.0000
-	.3937	10.0000	-	1.0236	26.0000	2-1/16	2.0620	52.3880
13/32	.4060	10.3190	1-1/32	1.0312	26.1940	-	2.0866	53.0000
-	.4130	10.5000	1-1/16	1.0620	26.9880	2-3/32	2.0940	53.1810
27/64	.4220	10.7160	-	1.0630	27.0000	2-1/8	2.1250	53.9750
-	.4331	11.0000	1-3/32	1.0940	27.7810	-	2.1260	54.0000
7/16	.4380	11.1130	-	1.1024	28.0000	2-5/32	2.1560	54.7690
29/64	.4530	11.5090	-	1.1250	28.5750	-	2.1650	55.0000
15/32	.4690	11.9060	1-1/8	1.1417	29.0000	2-3/16	2.1875	55.5630
-	.4724	12.0000	-	1.1560	29.3680	-	2.2047	56.0000
31/64	.4840	12.3030	-	1.1811	30.0000	2-7/32	2.2190	56.3560
-	.4920	12.5000	1-3/16	1.1875	31.1630	-	2.2440	57.0000
1/2	.5000	12.7000	1-7/32	1.2190	30.9560	2-1/4	2.2500	57.1500

Conversion

Conversion Chart

INCHES FRCTN.	DEC.	MM	INCHES FRCTN.	DEC.	MM
2-9/32	2.2810	57.9440	3-3/8	3.3750	85.7250
-	2.2835	58.0000	-	3.3858	86.0000
2-5/16	2.3120	58.7380	3-13/32	3.4060	86.5190
-	2.3228	59.0000	-	3.4252	87.0000
2-11/32	2.3440	59.5310	3-7/16	3.4380	87.3130
-	2.3622	60.0000	-	3.4646	88.0000
2-3/8	2.3750	60.3250	3-15/32	3.4690	88.1060
-	2.4016	61.0000	3-1/2	3.5000	88.9000
2-13/32	2.4060	61.1190	-	3.5039	89.0000
2-7/16	2.4380	61.9130	3-17/32	3.5310	89.6940
-	2.4409	62.0000	-	3.5433	90.0000
2-15/32	2.4690	62.7060	3-9/16	3.5620	90.4877
-	2.4803	63.0000	-	3.5827	91.0000
2-1/2	2.5000	63.5000	3-19/32	3.5940	91.2810
-	2.5197	64.0000	-	3.6220	92.0000
2-17/32	2.5310	64.2940	3-5/8	3.6250	92.0750
-	2.5590	65.0000	3-21/32	3.6560	92.8960
2-9/16	2.5620	65.0880	-	3.6614	93.0000
2-19/32	2.5940	65.8810	3-11/16	3.6875	93.6630
-	2.5984	66.0000	-	3.7008	94.0000
2-5/8	2.6250	66.6750	3-23/32	3.7190	94.4560
-	2.6380	67.0000	-	3.7401	95.0000
2-21/32	2.6560	67.4690	3-3/4	3.7500	92.2500
-	2.6772	68.0000	-	3.7795	96.0000
2-11/16	2.6875	68.2630	3-25/32	3.7810	96.0440
-	2.7165	69.0000	3-13/16	3.8125	96.8380
2-23/32	2.7190	69.0560	-	3.8189	97.0000
2-3/4	2.7500	69.8500	3-26/32	3.8440	97.6310
-	2.7559	70.0000	-	3.8583	98.0000
2-25/32	2.7810	70.6439	3-7/8	3.8750	98.4250
-	2.7953	71.0000	-	3.8976	99.0000
2-13/16	2.8125	71.4376	3-29/32	3.9062	99.2190
-	2.8346	72.0000	-	3.9370	100.0000
2-27/32	2.8440	72.2314	3-15/16	3.9375	100.0130
-	2.8740	73.0000	3-31/32	3.9690	100.8060
2-7/8	2.8750	73.0250	-	3.9764	101.0000
2-29/32	2.9062	73.8190	4	4.0000	101.6000
-	2.9134	74.0000	4-1/16	4.0620	103.1880
2-15/16	2.9375	74.6130	4-1/8	4.1250	104.7750
-	2.9527	75.0000	-	4.1338	105.0000
2-31/32	2.9690	75.4060	4-3/16	4.1875	106.3630
-	2.9921	76.0000	4-1/4	4.2500	107.9500
3	3.0000	76.2000	4-5/16	4.3120	109.5380
3-1/32	3.0312	76.9940	-	4.3307	110.0000
-	3.0315	77.0000	4-3/8	4.3750	111.1250
3-1/16	3.0620	77.7880	4-7/16	4.4380	112.7130
-	3.0709	78.0000	4-1/2	4.5000	114.3000
3-3/32	3.0940	78.5810	-	4.5275	115.0000
-	3.1102	79.0000	4-9/16	4.5620	115.8880
3-1/8	3.1250	79.3750	4-5/8	4.6250	117.4750
-	3.1496	80.0000	4-11/16	4.6875	119.0630
3-5/32	3.1560	80.1690	-	4.7244	120.0000
3-3/16	3.1875	80.9630	4-3/4	4.7500	120.6500
-	3.1890	81.0000	4-13/16	4.8125	122.2380
3-7/32	3.2190	81.7560	4-7/8	4.8750	123.8250
-	3.2283	82.0000	-	4.9212	125.0000
3-1/4	3.2500	82.5500	4-15/16	4.9375	125.4130
-	3.2677	83.0000	5	5.0000	127.0000
3-9/32	3.2810	83.3440			
-	3.3071	84.0000			
3-5/16	3.3120	84.1377			
3-11/32	3.3440	84.9314			
-	3.3464	85.0000			